

FIG. 1








FIG. 2



ERROR AT THE TIME OF INSTALLATION
 DEFORMATION DUE TO AGING AND THERMAL VARIATION
 (DEFORMATION OF HIGH TEMPERATURE PIPE)
 (NOTE THAT A SPACE BETWEEN THE WEDGE AND
 THE PIPE IS FILLED WITH HIGHLY VISCOUS GREASE
 OR METAL COUPLANT)




F I G. 4



5 / 9

FIG. 5



F I G. 6




FIG. 7




FIG. 8




FIG. 9

